HABS No. NY-5715-13

Governors Island, Commissary Storehouse (Officers Quarters, Building #3) Nolan Park Governors Island New York Harbor New York City New York County New York

HARS MY 31-GOVI,

PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, DC 20013-7127

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


44785 144 31-601,

ARCHITECTURAL DATA FORM

STATE New York	COUNTY New York			sland, New York Harbo
HISTORIC NAME OF STRUCTURE (INCL Governors Island, Commiss		NAME)	New York Ci	HAB\$ NO.
GOVERNOIS ISTANCE, COMMISS	ary broremouse	-		NY-5715-13
SECONDARY OR COMMON NAMES OF STRUCTURE				
Officers' Quarters, Building #3				
COMPLETE AODRESS (DESCRIBE LOCATION FDR RURAL SITES) Nolan Park, Governors Island, New York Harbor, New York County, New York, New York				
OATE OF CONSTRUCTION (INCLUDE SDURCE) 1846 US Army Real Property Records		ARCHITECT(S) (INCLUDE SDURCE) Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE DRIGINAL USE OF STRUCTURE) Throughout 1842, the need for more storage was a pressing problem for the post. In 1846, this simple structure was built and was used both as a commissary storehouse and a quarter-master storehouse. Its scale relates to the other buildings located around Nolan Park.				
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) The walls are brick, load bearing. The roof is a gable roof.				
SHAPE ANO OIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Originally the structure was a storehouse with open interior space. These are shown on the following pages.				
EXTERIOR FEATURES OF NOTE The structure is of brick with stepped gable ends.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLDOR PLANS, IF NDT SKETCHED) In 1922, the structure was converted to officers' quarters so probably the interior has no original features.				
MAJOR ALTERATIONS AND ADDITIONS WITH OATES				
In 1922, the interiors were remodeled into officers' housing.				
PRESENT CONDITION AND USE				
It is currently being used for housing and its condition is good.				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (INCLUDING LISTING DN NATIONAL REGISTER STATE REGISTERS, ETC.)				
SOURCES OF INFORMATION (INCLUDING LISTING DN NATIONAL REGISTER, STATE REGISTERS, ETC.) Historic Structures Inventory, Governors Island National Landmark nomination for Governors Island				
National Archives, Washington, DC, Record Group 92, Box 191, Army and Old Navy Branch				
COMPILER, AFFILIATION				DATE
Katherine Grandine, Histori	an, HABS			September 1985



Photocopy of Plan for Building #3
National Archives, Architecture and Cartographic Branch
Record Group 77-Fortifications File (Miscellaneous)
Fort Jay, New York, #15
Plan of Quartermaster and Commissary Storehouse
Unknown Delineator, ca. 1846-75



Photocopy of Plans for Building #3
National Archives, Architecture and Cartographic Branch
Record Group 77-Miscellaneous Forts File
Fort Jay, New York, #35
Plan of Quartermaster and Commissary Storehouse
Unknown Delineator, 1871



Reprint of Photograph of Building #3
National Archives, Still Photos Division
Record Group 165-C-235
View of Northeast Corner
Unknown Photographer, 1864